

QUAYS AND CAISSON STATUS UNDERWATER SURVEY IN THE COMMERCIAL BASIN PORT OF TERMINI IMERESE, PALERMO, ITALY

CLIENT: PORT AUTHORITY OF PALERMO



LOCATION: Termini Imerese, Palermo, Italy

YEAR: 2007


BUDGET: € 19,5000

PROVIDED SERVICES:



- morpho-bathymetric and stratigraphic survey.
- caisson damage analysis



LAPTOP AND ACQUISITION UNIT





TRANSDUCER




TRANSDUCER




SURVEY PLAN



DETAILS OF CAISSON DAMAGE



IMAGES OF SCAN ANALYSIS



SUBBOTTOM EQUIPMENT